


CCI Use of PS12-1 Power Supply on HCSII



CAUTION

The PS12-1 is protected by an internal fuse. Shorting the supply or drawing more than 1.5A of current will cause the fuse to blow. If the fuse is blown the user may elect to replace it himself or return the unit to CCI for repair at a cost of \$7.50. Please request an RMA number from CCI before returning the unit.